RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11733

RECEIVED FROM PLANT #9

DATE REC'D 3-30-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	5	116	0	23					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
5	737793 Cam Center Exposure Oblique IPS #A002898	5		

RECEIVED BY J Barcelos INSPECTED BY DATE 3-30-57 REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1069

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11737

RECEIVED FROM PLANT #9

DATE REC'D 3-30-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322		70	0	23					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
10	732023 Retainer Brake TS# #A002505	10	—	

RECEIVED BY J Barcelos INSPECTED BY DATE 4-1-57 REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1069